

POOR ORIGINAL

ENCLOSURE 1

NOTICE OF VIOLATION

License No. DPR-50

Based on the results of a NRC inspection conducted on February 24-27, 1975 it appears that one of the activities was not conducted in full compliance with conditions of your license as indicated below:

Contrary to Criterion III, Appendix B, 10 CFR 50 and the FSAR Section 1A, Operating Quality Assurance Plan, Section III, plant design change C/M 0800, Modification of Diesel Generator Air Start System, was completed during 1974 without receiving prior Generation Engineering Department review and approval as required by Generation Engineering Procedure GP 1003, Control of Design Changes.

This infraction was identified by the inspector and had the potential for causing or contributing to an occurrence with safety significance.

90012345

7910190 583