

Brown Boveri

BBC
BROWN BOVERI

Switchgear Products Group

June 6, 1985

BBC Brown Boveri, Inc.
Spring House, PA 19477
Phone: (215) 628-7400

Mr. R. C. DeYoung, Director
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, D C 20555

Subject: Supplement to:
BBC Brown Boveri K-Line Circuit Breaker
with Overcurrent Trip Device
Model OD-4 or OD-5
(10CFR Part 21 Reports)

Dear Mr. DeYoung:

This report is to supplement the BBC Brown Boveri 10CFR Part 21 Report on the same subject dated May 13, 1985.

Enclosed is a list of additional overcurrent trip devices that were furnished as spare part assemblies and circuit breakers, also furnished as spares, that could have an incorrect short time delay band lever (link) that had been inadvertently installed in the electro-mechanical overcurrent trip devices (Model OD-4 and OD-5 only) manufactured between October, 1983 and March, 1985

These items also require inspection and replacement of the link if it is found to be incorrect. As before, if the correct link (Part Number 707970 K1) is required it can be ordered through the local district office of BBC Brown Boveri at no charge.

BBC Brown Boveri is sending a copy of this report to all Nuclear Stations utilizing K-line circuit breakers in Nuclear and Non-Nuclear applications, since it is recommended that all K-line circuit breakers utilizing the OD-4 or OD-5 and OD-4 or OD-5 spare overcurrent trip assemblies manufactured between October, 1983 and March, 1985 be inspected for this reported condition.

A. F. KAISER

A. F. KAISER
President
Switchgear Products Group

AFK/jm

Enclosure

cc: A. V. Boetticher
F. M. D'Antonio
J. A. Huntsman
E. W. Rhoads
G. H. Rodney
L. H. Schmidt
G. H. Taylor

8506110334 850606
PDR ADOCK 05000280
S PDR

IE19
1/1

ADDITIONAL BBC BROWN BOVERI SPARE OD-4, OD-5, AND K-1600 CIRCUIT BREAKER WITH OD-4
IN NUCLEAR APPLICATIONS MANUFACTURED BETWEEN OCTOBER 1983 AND MARCH 1985

<u>DATE MANUFACTURED</u>	<u>USER</u>	<u>SALES ORDER</u>	<u>PURCHASE ORDERS</u>	<u>(QTY)</u>	<u>ITEM</u>
Nov. 1984	Cleveland Electric Illuminating Perry Nuclear Plant	37-05762	Q-2885-69	(11)	OD-4
Feb. 1985	Gulf States Utilities River Bend	37-06507	8A-1Q-78778	(1)	OD-4
Nov. 1983	Public Service New Hampshire Seabrook	33-03923	365002	(9)	OD-4
Jan. 1984	BBC Brown Boveri Hartford, Conn. (Seabrook)	33-04267	HT-00443-01	(2)	OD-5
Jan. 1984	Carolina Power & Light Brunswick Plant	33-04330	786531AX	(8) (16)	OD-5 OD-4
Feb. 1985	Stone & Webster Niagara Mohawk Nine Mile Point #2	33-04549	NMP-2E015N-20	(6)	OD-4
Sept. 1984	Duquesne Light Co. Beaver Valley	33-05527	C500244	(1)	OD-4
Sept. 1984	Virginia Electric Power Surrey Station	33-05423	1P 67295	(1)	OD-4
Aug. 1984	Florida Power & Light St. Lucie Plant	33-05383	12619-79901W	(1)	OD-4
May 1984	Stone & Webster Niagara Mohawk Nine Mile Point #2	33-04867	NMP2-FPO-20458	(2)	OD-4
May 1984	Arkansas Power & Light Arkansas Nuclear One	33-04905	07199	(3)	OD-4

ADDITIONAL BBC BROWN BOVERI SPARE OD-4, OD-5, AND K-1600 CIRCUIT BREAKER WITH OD-4
IN NUCLEAR APPLICATIONS MANUFACTURED BETWEEN OCTOBER 1983 AND MARCH 1985

<u>DATE MANUFACTURED</u>	<u>USER</u>	<u>SALES ORDER</u>	<u>PURCHASE ORDERS</u>	<u>(QTY)</u>	<u>ITEM</u>
Feb. 1985	Stone & Webster Niagara Mohawk Nine Mile Point #2	37-06431	NMP2-FPO-22782	(1)	OD-5
March 1985	Arkansas Power & Light Arkansas Nuclear One	37-06206	22080	(1)	OD-4
Jan 1985	Public Service New Hampshire Seabrook Station	37-06121	SNH-177 9763.006 145, -3, CO #70	(3)	OD-4
Oct. 1984	Georgia Power Company Plant Vogtle	37-05721	PAV-91 CO #24	(2) (2)	OD-4 K-1600 CB with OD-4
Oct. 1984	Georgia Power Company Plant Vogtle	37-05719	PAV-2146 CO #25	(2)	K-1600 CB with OD-4