

DCD/DCB

NOV 24 1992

The Marion Steel Company  
ATTN: Mr. Scott Conway  
Plant Manager  
912 Cheney Avenue  
Marion, OH 43302

License No. 34-21123-01  
Docket No. 030-19814

Dear Mr. Conway:

SUBJECT: REPORT OF CASTER SPILL INVOLVING 2 mCi <sup>60</sup>Co SOURCE

This acknowledges receipt of your letter dated September 18, 1992, describing an incident at your plant that involved the rupture of a 2 mCi <sup>60</sup>Co source.

Your response to this incident including planned preventive actions, such as the conversion to tungsten rather than stainless steel for the dip tube, will be reviewed during a future NRC inspection.

If you have any questions concerning this letter, please contact me at (708) 790-5624. We appreciate your cooperation.

Sincerely,

B. J. Holt, Chief  
Nuclear Materials Safety  
Section 1

cc: DCD/DCB (RIDS)

RI11  
Barry/sd

RI11  
Holt

100023

9212100110 921124  
PDR ADOCK 03019814  
C PDR

IE 07