

QUALITY ASSURANCE PROGRAM

OF

METILS, INC.

LICENSE NUMBER 42-16534-01

FOR COMPLIANCE WITH 10 CFR PART 71, APPENDIX E

1. ORGANIZATION

The final responsibility for the Quality Assurance (QA) Program for Part 71 Requirements rests with METILS, INC.

Design and Fabrication shall not be conducted under this QA Program. The QA Program is implemented as shown on the attached organization chart.

The Radiation Safety Officer is responsible for overall administration of the program, training and certification, document control and auditing.

The Radiographers are responsible for handling, storing, shipping, inspection, test and operating status and record keeping.

2. QUALITY ASSURANCE PROGRAM

The management of METILS, INC., establishes and implements this QA Program. Training, prior to engagement, for all QA functions is required according to written procedures. QA Program revisions will be made according to written procedures with management approval. The QA Program will ensure that all defined QA procedures, engineering procedures, and specific provisions of the package design approval are satisfied. The QA Program will emphasize control of the characteristics of the package which are critical to safety.

The Radiation Safety Officer shall assure that all radioactive material shipping packages are designed and manufactured under QA Program approval by Nuclear Regulatory Commission for all packages designed or fabricated after July 1, 1978. This requirement can be satisfied by receiving a certification to this effect from the manufacturer.

3. DOCUMENT CONTROL

All documents related to a specific shipping package will be controlled through the use of written procedures. All document changes will be performed according to written procedure approved by management.

The Radiation Safety Officer shall insure that all QA functions are conducted in accordance with the latest applicable changes to the documents.

8506110658 850508
PDR ADOCK 07100338
C PDR

4. HANDLING STORAGE AND SHIPPING

Written safety procedures concerning the handling, storage and shipping of packages for certain special form radioactive material will be followed. Shipments will not be made unless all tests, certifications, acceptances, and final inspections have been completed. Work instructions will be provided for handling, storage, and shipping operations.

Radiography personnel shall perform the critical handling, storage and shipping operations.

5. INSPECTIONS, TEST AND OPERATING STATUS

Inspections, test and operating status of packages for certain special form radioactive material will be indicated and controlled by written procedures. Status will be indicated by tag, label, marking or log entry. Status of nonconforming parts or packages will be positively maintained by written procedures.

Radiography personnel shall perform the regulatory required inspections and tests in accordance with written procedures. The Radiation Safety Officer shall ensure that these functions are performed.

6. QUALITY ASSURANCE RECORDS


Records of package approvals (including references and drawings), procurement, inspections, tests, operating logs, audit results, personnel training and qualifications and records of shipments will be maintained. Descriptions of equipment and written procedures will also be maintained.

These records will be maintained in accordance with written procedures. The records will be identifiable and retrievable. A list of these records with their storage locations, will be maintained by the Radiation Safety Officer.


7. AUDITS

Established schedules of audits of the QA Program will be performed using written check lists. Results of audits will be maintained and reported to management. Audit reports will be evaluated and deficient areas corrected. The audits will be dependent on the safety significance of the activity being audited, but each activity will be audited at least once per year. Audit reports will be maintained as part of the quality assurance records.

9/4/84
DATE


Norman P. Lanier
Radiation Safety Officer

QUALITY ASSURANCE PROGRAM ORGANIZATION CHART FOR
METILS, INC.
LICENSE NUMBER 42-16534-01
FOR
COMPLIANCE WITH 10 CFR PART 71, APPENDIX E



DESCRIPTION OF RESPONSIBILITIES

1. PRESIDENT - General management of the company.
2. VICE PRESIDENT - Responsible for operations control of the company supervision of employees, cost control, job assignments, personnel relations.
3. RADIATION SAFETY OFFICER - Responsible for overall administration of the radiation safety program (including Quality Assurance), personnel radiation safety training and certification, document control, and auditing of the radiation safety program.
4. RADIOGRAPHERS - Responsible for using, storing, shipping, inspection, testing operating status, and record keeping of radioisotope sources and devices in accordance with written procedures of the company as approved by the Operations Manager and Radiation Safety Officer.