

DEC 03 1992

DCD/DCB

Sid Acharya, M.D.
2680 South Cleveland Avenue
St. Joseph, MI 49085

License No. 21-26352-01
Docket No. 030-32499

Dear Dr. Acharya:

This refers to the special inspection conducted by W. P. Reichhold (Region III) and R. Anderson (Office of Investigations) on April 3, 1992. This special inspection was performed to determine if your facility and equipment for using radioactive materials were the same as those described in your application for an NRC license.

The areas examined during the special inspection are addressed in the enclosed report. No violations were identified.

Thank you for your cooperation and the information you provided concerning this matter.

During the inspection, it was noted that the address on your NRC license is incorrect. The numbers in your address should be 2680 rather than 2860. We have received your letter dated November 11, 1992 requesting an amendment to correct your address. We will review this matter during our next inspection. Please be advised, that you must amend your license before you change any item that is currently approved in your license.

Sincerely,

John A. Grobe, Chief
Nuclear Materials Safety
Branch

Enclosure: Inspection Report
No. 92-001

cc w/enclosure:
DCD/DCB (RIDS)

RIII

Reichhold/bt

PIII

Shear

RIII

Grobe

921211-92 921203
PDR A JCK 03032499
C PDR

1 E07