

BLANDIN PAPER COMPANY

November 2, 1979

Nuclear Regulator Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Att: Mr. Samuel L. Pettijohn  
Regional Licensing Section  
Control No. 02312

Dear Mr. Pettijohn:

Attached find the supplemental information you requested  
in your letter dated October 23, 1979. I believe you will  
find the information complete.

If there are any further questions please contact me  
directly.

Yours very truly,

BLANDIN PAPER CO.

*John Thompson*  
and  
John Thompson  
Electrical Engineer

Enc.  
any

8001100182

6pp

CONTROL NO. 78626

BLANDIN PAPER COMPANY

Control No. 02312  
License No. 22-06952-02

Additional Sheets  
Form NRC-3131

#15 A

1. Precautions, restrictions and lockout procedures.

Access to the vicinity of the unshielded radiation is not possible without removal of an existing floor or by way of a sixteen foot ladder. For this reason operating personnel have no access to the radiation area.

If the device becomes ineffective the manufacturer, Kay-Ray, Inc., will service the units. In addition, there is a lockout on the source housing which would be utilized in the event of an emergency or equipment removal.

BLANDIN PAPER COMPANY

Control No. 02312  
License No. 22-06952-02

Additional Sheets  
Form NRC 313-1

#15 B

In the event of an emergency specific guidelines have been established to evacuate the building. See attached "Evacuation Plan". The tour boss supervisors have been informed to contact the following people in the event a problem occurs:

John Thompson - ext. 270  
Home 326-3089

Bob Holycross - ext. 364  
Home 326-0770

GENERAL NOTICE  
EMERGENCY EVACUATION PLAN

Due to an emergency situation, it may be necessary at some time for the mill to be evacuated. Reasons for such an emergency could be a fire, gas leak, chemical exposure, etc. The following plans were developed to have a systematic and orderly response to such an emergency. Please read and adhere to these procedures for your own well-being and protection.

1. In the event of an emergency in the mill, immediately notify your tour boss on duty.
2. If the emergency involves a fire, the tour boss or nearby member of the Fire Brigade will make the decision to call out the mill Fire Brigade and/or the Grand Rapids Fire Department (326-3461).
3. To call for the mill Fire Brigade, pick up a P.A. microphone and slowly announce "FIRE, FIRE, FIRE; FIRE IN THE (location), FIRE, FIRE, FIRE; FIRE IN THE (location).
4. If the situation warrants calling for outside services, such as ambulance, Sheriff's Department, Police Department, or Fire Department, the call must be made through the Power House, unless an outside line is available. CALL EXTENSION 354, SLOWLY AND CLEARLY REPORT YOUR LOCATION, WHAT THE SITUATION IS, AND WHAT EMERGENCY SERVICES ARE NEEDED.
5. After calling for assistance, make sure someone is sent to the corner of Globe Drug Store to direct the emergency vehicle to the closest entrance and specific location of the problem area.
6. The decision to evacuate the mill will be made by one of the following people:

President/Harold Zigmund

Vice President of Operations/Earl Wolleat

Production Manager/Clarence Blaine

Technical Manager/John Ward

Industrial Relations Manager/John Reif

If none of these people are on the mill premises, a call must be made to one of them to authorize an evacuation.

**CONTROL NO. 7 8 6 2 6**

7. Evacuation orders will be given over the P.A. system. Follow the exit plan and route as indicated on the permanently posted evacuation notice for each department area.
8. IT IS EXTREMELY IMPORTANT THAT EVERYONE PROCEED TO AND REMAIN AT THEIR DESIGNATED STAGING AREAS. This allows for an orderly method of verifying that all employees have been safely evacuated. Each tour boss and/or department head will take a head count of the employees in their respective departments and report their findings to the people in charge of emergency services.
9. After initiating a mill evacuation or some other major emergency situation arises during an afternoon, night or weekend, attempts should be made to contact the following people:
- |                 |          |                   |          |
|-----------------|----------|-------------------|----------|
|                 |          | John Thompson     | 326-3089 |
| Earl Wolleat    | 326-0096 | John Muhar        | 326-2945 |
| Clarence Blaine | 326-2446 | Dennis Schaar     | 326-3020 |
| John Ward       | 326-9096 | Phyllis Gornowich | 326-4974 |
| John Reif       | 326-0616 | Sharon Stevens    | 326-8153 |
| Bob Holycross   | 326-0770 |                   |          |
10. The order to re-enter the mill will be made by one of the five who are authorized to order an evacuation. The order will not be given until an all-clear situation has been determined by emergency services personnel.

It is hoped that it will never be necessary to implement the above procedures. If required, however, we trust that everyone will act responsively and cooperate with the people in charge. If you have any questions about what to do in the event of an emergency, contact your department head or Safety Administrator.

# Emergency Evacuation Plans

- Sample*
- Exit this dept. via \_\_\_\_\_
  - Move away from building
  - Proceed to \_\_\_\_\_
  - Do not re-enter area unless  
all-clear signal has been given  
by emergency services  
personnel
  - Alternate route \_\_\_\_\_

CONTROL NO. 7 8 6 2 6