



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

DEC 7 1992

Docket No. 15000042
License No. General License 150.20

Robco Production Logging, Inc.
ATTN: William H. Robinson, President
P.O. Box 1423
1001 East Highway
Snyder, Texas 79549

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 15000042/92-02 (NOTICE OF VIOLATION)

This refers to the inspection conducted by Mr. Selvan Rajendran of this office on November 12, 1992, conducted in NRC jurisdiction under the terms of 10 CFR 150.20, using Byproduct License No. LO 3549 issued by the state of Texas. At the conclusion of the inspection, the findings were discussed with members of your staff.

The inspection was an examination of activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, and interviews of personnel.

As discussed during the inspection, before using your shipping container as a Type-7A container, you must perform the tests specified in 49 CFR 173.465 and 173.466 (enclosed). The records of these tests should be kept in your file for review during a future inspection.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice).

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

Also reviewed were the actions you had taken with respect to the violations observed during our previous inspection conducted on December 8, 1982, and November 26, 1990. The inspection verified that the corrective actions for

100000
9212140012 921207
PDR STPRG EMV PDR
PDR

TE07

bcc.

DMB - Original (IE-07)

JLMilhoan

LJCallan

JPJaudon

MRodriguez, OC/LFDCB (4503)

*WLFisher

*CLCain

*SRajendran

*NMLS

*MIS System

*RIV Files (2)

*REHall, URFU

RWISE, AC

*W/IFS Form

RIV:NMLS <i>se</i>	C:NMLS	D:DRSS <i>12/3</i>		
SRajendran	WLFisher <i>12/4</i>	LJCallan <i>12/7</i>		
<i>12/3/92</i>	<i>12/4/92</i>	<i>12/7/92</i>		


these violations had been implemented as stated in your replies dated January 28 and March 13, 1991, and that these actions were effective.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

The responses directed by this letter and the enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96.511.

Should you have any questions concerning this letter, please contact the inspector identified above at (817) 860-8100.

Sincerely,


L. J. Gallan, Director
Division of Radiation Safety
and Safeguards

Enclosures:

1. Appendix - Notice of Violation
2. 10 CFR Part 19
3. 10 CFR Part 20
4. 10 CFR Part 30
5. 10 CFR Part 39
6. 10 CFR Part 71
7. 10 CFR Part 150
8. 10 CFR Part 170
9. NRC Form 241
10. NRC Form 3

cc:
Texas Radiation Control Program Director

bcc:

DMB - Original (IE-07)

JLMilhoan

LJCallan

JPJaudon

MRodriguez, OC/LFDCB (4503)

*WLFisher

*CLCain

*SRajendran

*NMLS

*MIS System

*RIV Files (2)

*REHail, URFO

RWIS, AC

*W/IRs Form

RIV:NMLS <i>sl</i>	C:NMLS	D:DRSS <i>sl</i>		
SRajendran	WLFisher <i>sl</i>	LJCallan <i>sl</i>		
12/3/92	12/4/92	12/7/92		