

11-2-81

Memorandum For: D. W. Lett
Reactor Inspector

Thru: F. Wencelawski, Chief
Reactor Radiation Safety Section

From: G. Yuhas
Radiation Specialist, RRSS

Subject: Response to Items 6 of
ASLB Order DN-50-132-OLA
dated October 20, 1981

The following information is provided
for use in preparation of the Region
II Response.

The complete inspection program
described by MC 5515 is being performed
by RRSS. This includes modules 80710,
82710, 82711, 82712, 83740, 83745, 84711,
85718 and 86740.

No changes in inspection frequency
or content have been made and

none are planned.

During 1980 and 81 three inspections were performed as noted below.

<u>Dates of Inspection</u>	<u>Inspection Report No</u>	<u>Findings of Non Compliance</u>
March 24-28, 1980	50-133/80-01	10CFR20.203(c)(1) 10CFR20.203(d)(iii) 10CFR20.203(f)
December 1-5, 1980	50-133/80-04	10CFR71.5
June 29-July 2, 1981	50-133/81-03	T.S. VIII B.4

RRSS takes the position that until final disposition of the Unit is determined we expect the licensee to maintain an radiation protection program appropriate to the amount of ^{work} activity within the restricted area.

GPJhes.