



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

June 10, 1985

Docket No. 50-302

Florida Power Corporation
ATTN: Mr. Walter S. Wilgus
Vice President
Post Office Box 14042
St. Petersburg, Florida 33733

Gentlemen:

SUBJECT: INSPECTION NO. 50-302/85-09

Enclosed is the report of the special team inspection conducted by Mr. R. C. Wilson and other NRC representatives on March 4-8, 1985, at the Crystal River 3 site of Florida Power Corporation of activities authorized by NRC License No. DPR-72. The team's findings were discussed with you and members of your staff at the conclusion of the inspection. The inspection reviewed your implementation of a program as required by 10 CFR 50.49 for establishing and maintaining the qualification of electric equipment within the scope of 10 CFR 50.49. The inspection also included evaluations of the implementation of equipment qualification corrective action commitments made as a result of the January 11, 1983, Safety Evaluation Report (SER) and the October 1, 1982, Franklin Research Center Technical Evaluation Report (TER). Within this area, the inspection consisted of examinations of selected procedures and records, interviews with personnel, and observations by the inspectors.

You stated that you plan to complete implementation of your program for meeting the requirements of 10 CFR 50.49 by the end of the refueling outage that began March 9, 1985. The inspection determined that you have made considerable progress toward completing that plan, but a substantial amount of work must be performed before restart. The Qualification Documentation Files generally were deficient because they lacked some necessary information, although much of that information was provided during the inspection in response to questions. Qualification of several components has not yet been established pending resolution of additional concerns detailed in the Inspection Report, but no equipment was found to be not qualified. Your Qualification Maintenance Program Manual was found to be generally satisfactory, but only one of the implementing procedures was in effect. Your master list was found to be adequate.

8506120225 850610
PDR ADOCK 05000302
G PDR

FOI'S PROCESSING

Original document not available to ERIC

Certified by Sherry Meador


IE01
11

June 10, 1985

The enclosed Inspection Report describes eight Open Items. Your actions concerning these items will be addressed in a future NRC inspection. You should carefully review the inspection findings and take appropriate action so as to achieve full compliance with the requirements of 10 CFR 50.49 prior to restart from your March 9, 1985 outage, since noncompliance with 10 CFR 50.49 requirements after that time will result in enforcement action.

We are available to discuss any questions you have concerning this inspection.

Sincerely,

A handwritten signature in dark ink, appearing to read "Gary G. Zech", written in a cursive style.

Gary G. Zech, Chief
Vendor Program Branch
Division of Quality Assurance, Vendor,
and Technical Training Center Programs
Office of Inspection and Enforcement

Enclosure:
Inspection Report No. 50-302/85-09

June 10, 1985

DISTRIBUTION:

DCS
PDR
VPB Reading
DQAVT Reading
JTaylor
RVollmer
BKGrimes
UPotapovs
GHubbard
GHolahan, NRR/ORAB
RWilson
RLaGrange, NRR/EOB
HGarg, NRR/EOB
RKarsch, NRR/ORAB
HSilver, NRR/DL
M. Yost, Idaho National Engineering Laboratory
LBustard, Sandia National Laboratories
LFoster, RII
AHerdt, RII
NMerriweather, RII
JThomas, DPC

RCW
VPB:DQAVT
RWilson:sam
5/30/85

4P
SC/VPB:DQAVT
UPotapovs
5/30/85

37
BC/VPB:DQAVT
GGZech
6/3/85

37
DIR:DQAVT
BKGrimes
6/7/85

per telecon
B. Karsch
BC/ORAB:NRR
GHolahan
5/3/85
6
~~DIR:DIE~~
~~JMTaylor~~
~~5/1/85~~

per telecon
H. Garg
ABC/EOB:NRR
RLaGrange
5/3/85
6

per telecon
L. Foster
RII
ARHerdt
5/4/85
6