


RE: 92326-N

December 4, 1992

**AIRBORNE EXPRESS**

Mr. James I. Milhoan  
Regional Administrator  
U.S. NUCLEAR REGULATORY COMMISSION  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011




RE: License No. SUB-1010; Docket No. 40-8027  
Report Pursuant to Order Modifying License,  
dated March 13, 1992

Dear Mr. Milhoan:

Pursuant to the requirements of the March 13, 1992 Order Modifying License, attached is the Sequoyah Fuels Corporation (SFC) written report of incidents or events specified by the Order. This report includes events identified since SFC's report of November 25, 1992. This report is consistent with the April 3, 1992 Confirmatory Order which altered the March 13, 1992 Order Modifying License.

If there are any questions regarding this report, please contact me at 918/489-3207.

Sincerely,



John S. Dietrich  
Vice President  
Regulatory Affairs

JSD:lh

Attachment

9212150034 921204  
PDR ADOCK 04008027  
C PDR

93-0391

IE-58  
IV-5

Sequoyah Fuels Corporation  
Reportable Events Pursuant to  
March 13, 1992 Order Modifying License  
Report No. OML 92-37  
Period Ending December 4, 1992

- A. Failure to follow procedures or other requirements where there are indications that the cause was a deliberate failure to meet requirements. A deliberate failure is a failure caused by deliberate misconduct as defined in 10 CFR 40.10(c).

None for this report.

- B. Spills or other unusual occurrences involving the spread of contamination in and around the SFC's facility, equipment, or site, subject to 10 CFR 40.36(f)(1).

None for this report.

- C. Any occurrence which leads to 1) offsite release or contamination in unrestricted areas in excess of SFC's administrative limits; 2) any contamination in restricted areas that requires activities in an area to be suspended for more than 8 hours pending decontamination; or 3) any personnel contamination in excess of SFC's administrative limits which within one hour of detection is not reduced to within limits.

C-1

A box of old security badges were found in a cabinet at the Carlile School (Rm 103) on December 3, 1992. The personnel who found the badges requested a survey and a few of the badges were found to contain fixed contamination above the SFC administrative limit (5,000 dpm/100cm<sup>2</sup>). The maximum identified fixed contamination was 15,000 dpm/100cm<sup>2</sup> beta/gamma. No fixed alpha contamination was identified above SFC administrative limits and no removable contamination was identified above SFC administrative limits. The box of badges was promptly moved to the restricted area. The badges did not contribute any measurable exposure to personnel or the public.

C-2 and C-3; None for this report.

- D. Employee concerns or allegations that any of the above failures may have occurred unless it is determined within the above five working days that the concern or allegation is not valid.

None for this report.

- E. Any other matter that the president, SFC, believes rises to a regulatory or safety concern that warrants NRC notification.

None for this report.