

CONTROL BLOCK (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 P A B V S 1 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 4 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CON'T  
01 REPORT SOURCE L 0 5 0 0 0 0 3 3 4 7 0 R 1 6 7 9 0 1 0 7 8 0 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
02 At 0635 hours, the 1C Charging Pump was started for an operability verification  
03 following maintenance. At 0738 hours, a high temperature alarm was received for the  
04 1C Charging Pump thrust bearing. The 1C Charging Pump was shutdown at 0742 hours.  
05 An investigation revealed a river water supply valve to the charging pump speed  
06 increaser had been inadvertently left shut following maintenance. This resulted in  
07 overheating of the speed increaser bearings and lube oil pump. The bearing and lube  
08 oil pump were replaced and the pump was run satisfactorily.  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

09 SYSTEM CODE S F 11 CAUSE CODE A 12 CAUSE SUBCODE C 13 COMPONENT CODE V A L V E X 14 COMP. SUBCODE E 15 VALVE SUBCODE D 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

17 LER NO REPORT NUMBER 7 9 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

ACTION TAKEN H 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NRC-4 FORM SUB N 24 PRIME COMP SUPPLIER Z 25 COMPONENT MANUFACTURER Z 9 9 9 9 26  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
13 The incident resulted from a failure of Maintenance and Operations personnel to  
14 insure the charging pump was returned to service satisfactorily following  
15 maintenance activities. The personnel involved received written reprimands for  
16 their actions. All Maintenance and Operations personnel were apprised of the  
17 incident and its consequences.  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

15 FACILITY STATUS G 28 POWER 0 0 0 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance test after maintenance  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

16 ACTIVITY CONTENT Z 32 RELEASED OF RELEASE Z 33 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

17 PERSONNEL EXPOSURES NUMBER 0 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

18 PERSONNEL INJURY NUMBER 0 0 0 0 40 DESCRIPTION N/A 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

20 ACTIVITY DESCRIPTION N/A 44  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

POOR ORIGINAL

90017210

8001140 416

NRC USE ONLY