

# LICENSEE EVENT REPORT

POOR ORIGINAL

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

REPORT SOURCE 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
 During surveillance testing of 2/3 D/G, pinion gears engaged, starting the D/G. At 200 RPM pinion gears remained engaged, but they eventually disengaged prior to D/G reaching full speed. Failure to start alarm was received. D/G was immediately de-energized to prevent pinion gears from being damaged. Health and safety of public were not affected because redundant systems were verified operable by required testing. This event is the first of its kind.

SYSTEM CODE 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (37)  
 Probable cause was bad connection in speed sensing circuit, preventing deenergizing start solenoid and disengaging gears. A suspected bad capacitor was replaced, but removed capacitor subsequently tested satisfactorily. D/G was successfully started and loaded to full power. No further corrective action deemed necessary.

POWER 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

ROUTINE SURVEILLANCE TESTING (32)

90022233

8001150634

NAME OF PREPARED Atif A. Ammar