

FILE COPY

JUN 5 - 1985

Mahendra C. Parekh, M.D.  
1816 Chapel Drive  
Suite I  
Findlay, OH 45840

Dear Dr. Parekh:

Enclosed is Amendment No. 01 to your NRC License Number 34-24454-01 in accordance with your request.

Please note that your license still does not authorize you to install remove, exchange or leak test the iodine-125 and gadolinium-153 sources contained in your bone mineral analyzers. When submitting documentation to our office showing that you have been trained in these procedures, please write the following statement on your cover letter: "This Is Additional Information, Not A New Amendment Request".

In view of this amendment, please review your license carefully to assure that you understand and are in compliance with the terms and conditions contained therein. If you have questions, please contact our office by dialing (312) 790-5625.

Sincerely,

Original Signed By  
B.J. Holt  
Materials Licensing Section

Enclosure: Amendment No. 01

8506180398 850604  
REG3 LIC30  
34-24454-01 PDR

RIII

Holt/cm  
05/30/85

hg  
6/2/85