




ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

May 15, 1985



ØCANØ585Ø8

Mr. D. R. Hunter, Chief
Reactor Project Branch #2
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

SUBJECT: Arkansas Nuclear One - Units 1 & 2
Docket Nos. 50-313 and 50-368
License Nos. DPR-51 and NPF-6
Notices of Violation and Deviation,
Inspection Report 50-313/85-02, 50-368/85-02

Gentlemen:

AP&L has reviewed the program elements subject to the notice of violation and notice of deviation resulting from the inspection activities of February 4-8, 1985.

The corrective action either underway or anticipated to address the above notices is as follows:

Notice of Violation

Appendix A to inspection report 50-313/85-02, 50-368/85-02 (notice of violation) stated "no review and approval by the QA Manager had been conducted prior to the implementation and use of draft QAP-13, Revision 3 dated February 23, 1984 for the emergency preparedness audit conducted April 16 through July 2, 1984.

In response to that finding, the following actions have been taken:

1. We have recently completed a review of QAP-13 which verified that the procedure addresses the key elements of the emergency preparedness program. As QAP-13 is the basis for emergency preparedness audits, this assures that the key elements will be addressed during the 1985 audit.

IC-053/85

8506180466 850613
PDR ADOCK 05000313
PDR
Q

May 13, 1985

2. Form QAA-3/1, Rev. 2, used to review the QA procedure and identify necessary changes or revisions, has been modified to denote the necessity of approval of the QA Manager by title and accompanying signatures before a revised procedure is used. The form did not provide specific instructions for this approval previously.
3. The current QA Procedure, in preparation for the 1985 audit, has been reviewed, approved and signed off by the QA Manager. This action was complete as of 03/28/85 and we are now in compliance.

Notice of Deviation

Appendix B to inspection report 50-313/85-02, 50-368/85-02 (notice of deviation) stated "the revised QAP-13 checklist, which implements QA Procedure QAP-13, did not address the elements of 50.54(t) regarding an evaluation for adequacy of interfaces with State and Local governments."


In response to that finding, the following actions are planned:

1. Additional focus will be given, during the 1985 audit of emergency preparedness, to the interfaces with State and Local governments in accordance with 10CFR50.54(t). To this end, AP&L intends to use an outside technical specialist with an emergency planning background to assist QA with the review for adequacy of these interfaces.
2. A draft revision to QAP-13 will be developed following the completion of the 1985 audit of emergency preparedness. The purpose will be to incorporate any improvement items identified during the audit which would enhance the evaluation of those interfaces between AP&L, State and Local governments.
3. Compliance with this notice is projected for July, 1985.

AP&L believes that the actions previously outlined are responsive to the inspection findings and will result in bringing the QA program into compliance with the subject regulations.

Should you have any questions regarding this submittal, please contact my office.

Very truly yours,



J. Ted Enos
Manager, Licensing

JTE:MT:ds