

No. 2-81-21/3L

This LER concerns loss of one drywell pressure channel due to pressure transmitter malfunction. Governing Technical Specification is Table 3.1.1.

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 P A P B S 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
 7 8 9 14 15 25 26 30 37 CAT 38

CON'T
 0 1 REPORT SOURCE L 6 0 5 0 - 0 2 7 7 0 3 2 9 8 1 8 0 4 2 8 8 1 9
 7 8 9 14 15 25 26 30 37 CAT 38

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
 0 2 While at full power, annunciation indicated possible failure of an
 0 3 RPS/PCIS input. Investigation determined that the 'D' drywell pressure
 0 4 channel was malfunctioning. The channel was declared inoperable and the
 0 5 three remaining channels functionally tested and verified operable.
 0 6 Applicable Technical Specification is Table 3.1.1.
 0 7
 0 8
 0 9

SYSTEM * CODE I A (11) CAUSE CODE E (12) CAUSE SUBCODE G (13) COMPONENT CODE INSTRU (14) COMP SUBCODE T (15) VALVE SUBCODE Z (16)
 7 8 9 14 15 25 26 30 37 CAT 38

17 LER/RO REPORT NUMBER 8 1 EVENT YEAR 8 1 SEQUENTIAL REPORT NO. 0 2 1 OCCURRENCE CODE 0 3 REPORT TYPE L (15) REVISION NO. 0
 7 8 9 14 15 25 26 30 37 CAT 38

ACTION TAKEN A (18) FUTURE ACTION Z (19) EFFECT ON PLANT Z (20) SHUTDOWN METHOD Z (21) HOURS 0 0 0 0 ATTACHMENT SUBMITTED N (23) NPRO-4 FORM SUB Y (24) PRIME COMP. SUPPLIER N (25) COMPONENT MANUFACTURER R 3 7 0
 7 8 9 14 15 25 26 30 37 CAT 38

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
 1 0 The cause was determined to be an electronic failure in the Rosemount
 1 1 Model 1151 GP pressure transmitter which feeds trip unit PS 2-5-12D.
 1 2 Circuit boards on the transmitter were replaced and the instrument
 1 3 channel satisfactorily tested and returned to service on 3/30/81.
 1 4

FACILITY STATUS E (28) % POWER 1 0 0 OTHER STATUS Unit 3 S/D (30) METHOD OF DISCOVERY A (31) DISCOVERY DESCRIPTION Operator Observation (32)
 7 8 9 14 15 25 26 30 37 CAT 38

ACTIVITY RELEASED Z (33) CONTENT 2 (34) AMOUNT OF ACTIVITY N/A (35) LOCATION OF RELEASE N/A (36)
 7 8 9 14 15 25 26 30 37 CAT 38

PERSONNEL EXPOSURES NUMBER 0 0 0 TYPE Z (38) DESCRIPTION N/A (39)
 7 8 9 14 15 25 26 30 37 CAT 38

PERSONNEL INJURIES NUMBER 0 0 0 DESCRIPTION N/A (41)
 7 8 9 14 15 25 26 30 37 CAT 38

LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION N/A (43)
 7 8 9 14 15 25 26 30 37 CAT 38

PUBLICITY ISSUED N (44) DESCRIPTION N/A (45)
 7 8 9 14 15 25 26 30 37 CAT 38

NAME OF PREPARER M. J. Cooney PHONE (215) 841-5020

RECEIVED
 MAY 07 1981
 U.S. NUCLEAR REGULATORY COMMISSION

Aug 21

8105080280

5