



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

MAY 06 1981

TERA

Docket No. 50-309

Mr. Robert H. Groce
Senior Engineer - Licensing
Maine Yankee Atomic Power Company
1671 Worcester Road
Framingham, Massachusetts 01701



Dear Mr. Groce:

We have completed our review of your Guard Training Plan submitted by letter dated February 11, 1980. Our review has indicated the need for revisions and additional information contained in the enclosure. Please respond to the enclosure within 90 days after receipt of this letter.

Sincerely,

Robert A. Clark, Chief
Operating Reactors Branch #3
Division of Licensing

Enclosure: As stated

cc: See next page

f

8105120603

Maine Yankee Atomic Power Company

cc:

E. W. Thurlow, President
Maine Yankee Atomic Power Company
Edison Drive
Augusta, Maine 04336

Mr. Donald E. Vandenburg
Vice President - Engineering
Yankee Atomic Electric Company
20 Turnpike Road
Westboro, Massachusetts 01581

John A. Ritscher, Esquire
Ropes & Gray
225 Franklin Street
Boston, Massachusetts 02110

Mr. Rufus E. Brown
Deputy Attorney General
State of Maine
Augusta, Maine 04330

Mr. Nicholas Barth
Executive Director
Sheepscot Valley Conservation
Association, Inc.
P. O. Box 125
Alan, Maine 04535

Wiscasset Public Library Association
High Street
Wiscasset, Maine 04578

Mr. Torbet H. Macdonald, Jr.
Office of Energy Resources
State House Station #53
Augusta, Maine 04333

Robert M. Lazo, Esq., Chairman
Atomic Safety and Licensing Board
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dr. Cadet H. Hand, Jr., Director
Bodega Marine Laboratory
University of California
Bodega Bay, California 94923

Mr. Gustave A. Linenberger
Atomic Safety and Licensing Board
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mrs. L. Patricia Doyle, President
SAFE POWER FOR MAINE
Post Office Box 774
Camden, Maine 04843

First Selectman of Wiscasset
Municipal Building
U. S. Route 1
Wiscasset, Maine 04578

Stanley R. Tupper, Esq.
Tupper and Bradley
102 Townsend Avenue
Boothbay Harbor, Maine 04538

David Santee Miller, Esq.
213 Morgan Street, N. W.
Washington, D. C. 20001

Mr. Paul Swetland
Resident Inspector/Maine Yankee
c/o U.S.N.R.C.
P. O. Box E
Wiscasset, Maine 04578

Mr. Charles B. Brinkman
Manager - Washington Nuclear
Operations
C-E Power Systems
Combustion Engineering, Inc.
4853 Cordell Avenue, Suite A-1
Bethesda, Maryland 20014

Director, Criteria and Standards Division
Office of Radiation Programs (ANR-460)
U.S. Environmental Protection Agency
Washington, D. C. 20460

U.S. Environmental Protection Agency
Region I Office
ATTN: EIS COORDINATOR
JFK Federal Building
Boston, Massachusetts 02203

State Planning Officer
Executive Department
199 State Street
Augusta, Maine 04330

POOR ORIGINAL

Rec 4/1/80

14-1001

COMMENTS ON MAINE VOLUNTARY GUARD TRAINING PLAN

General Comments

A detailed review of the plan reflects that it requires revision in order to be acceptable. Specific comments concerning individual sections of the plan follow this section.

The implementation schedule outlined in your letter of August 17, 1979, must be incorporated as part of the plan. Moreover, a statement should be added to indicate that the plan will be followed 60 days after approval. This would make your implementation schedule consistent with the requirements of 10 CFR 73.55(b)(4).

Specific Comments

- 1.4.1 Delete the second sentence in this section since the Guard Training and Qualification Plan must apply to all members of your security force.
- 1.4.1.2 Revise this section to clarify that the medical consultant is a licensed physician as required by the regulation.

Add a commitment that if uncorrected distance vision is not at least 20/40 in the better eye, the individual shall carry an extra pair of corrective lenses when on duty.
- 1.4.1.3 The mental determination must be made by a licensed psychologist, psychiatrist, or physician or other person professionally trained to identify emotional instability. Confirm that the medical consultant meets these requirements. Additionally, the mental determination must be attested to and retained as part of the employment suitability documentation.
- 1.4.1.4 Correct "shorgun" to read "shotgun".
- 1.4.1.7 This section must be revised to include all requalification requirements as part of the documentation. Additionally, all documentation must be retained on site for a minimum of two years.
- 1.4.2 Clarify that the crucial tasks will be demonstrated to the security supervisor. Crucial task records to include requalification must be retained on site for a minimum of two years.
- 1.4.2.1 A commitment must be added to this section that contract security personnel will meet all employment suitability and qualification criteria of section 1.4.1.
- 1.4.2.1 Add additional tasks for the CAS operator to direct alarm assessment, and if appropriate, as well as to operate the card-key system.

POOR ORIGINAL

Task 34 Identify the specific areas of the vehicle to be searched as outlined in 73.55(h)(4).

- 1.4.4 The National Police course used for weapon qualification must be described in this section. Additionally, any equivalent course must also be described and approved before it may be utilized.

The course of fire used for shotgun qualification must also be described in this section.

- 1.4.5 The security equipment used or available to members of the security force must be identified in this section.

POOR ORIGINAL