

UNITED STATES ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE

1. LICENSEE Department of the Air Force USAF Special Weapons Center Kirtland Air Force Base Albuquerque, New Mexico 87117	2. REGIONAL OFFICE U. S. ATOMIC ENERGY COMMISSION REGION IV, DIVISION OF COMPLIANCE 10395 W. COLFAX, ROOM 200 DENVER, COLORADO 80215
3. LICENSE NUMBER License No. 30-03110-02 30-5481	4. DATE(S) OF INSPECTION March 11 and 12, 1968
5. The following activities under your license (identified in Item No. 3 above) appear to be in noncompliance with AEC regulations or license requirements, as indicated. a. Contrary to License Condition No. 18.C., which requires that sealed sources be tested for leakage and/or contamination at intervals of six months or less, the following deviations were noted: 1. The 5-curie cesium-137 sealed source was not tested between July 15, 1966 and April, 1967. 2. The 103-millicurie cesium-137 sealed source was not tested between February 3, 1966 and November, 1966. 3. The 400-curie cobalt-60, the 10-curie cobalt-60, and the 39-millicurie cobalt-60 sealed sources were not tested between July 15, 1966 and February 6, 1967, or between February 6, 1967 and October, 1967. 4. Two cesium-137 sealed sources of approximately 3 millicuries each were not tested between January 4, 1966 and February 9, 1967, or between February 9, 1967 and January, 1968. b. The records of leak test results have not been maintained in units of microcuries, as required by License Condition 18.D.	
Supplementary page <u>None</u> attached.	
ORIGINAL SIGNED by JAMES E. HYDER James E. Hyder AEC Compliance Inspector	
MAR 26 1968 Date	

8507300400 850530
PDR FOIA
BURR85-229 PDR

ORIGINAL: LICENSEE.

COPIES: ☐ CO REGION ☒ CO HEADQUARTERS ☐ L&R HEADQUARTERS.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-605311

882-995