



EASTERN WELL SURVEYS, INC.

3300 OLD AIRPORT ROAD
WOOSTER, OH 44691

29 GLENWOOD AVENUE
BRADFORD, PA 16701

December 4, 1992

U. S. Nuclear Regulatory Commission
Attn: Mr. B. J. Holt, Chief
Nuclear Materials Inspection, Sec. 1
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Ref.: Reply to a Notice of Violation.

License No. 34-12927-01 Docket No. 030-05849

1. VIOLATION: Condition 12. Of License names individuals authorized to act as logging supervisors or logging assistants.
EXPLANATION & CORRECTIVE ACTION: There was a misunderstanding of when the supervisors and logging assistants were to be listed on the license. I did not distinguish between authorization and qualification. Since there is normally a turn over of personnel, I was under the impression that the authorization was to be done at the time of license renewal. All of the persons listed in the violation have been qualified by their on the job training, attendance and certification from a formal school for well loggers. (Certificates on file). Corrective action will be a forth coming ammendment to our license naming these people by January 15, 1993.
2. VIOLATION: 10 CFR 39.61(c) requires the licensee to provide safety reviews for logging supervisors and logging assistants at least once during each calender year.
EXPLANATION & CORRECTIVE ACTION: Since we are a small company I have many opportunities to be on site with our supervisors. Reviews have been made, but I failed to document them. A form has been made to conform to the guide in the Appendix A, "Annual Inspection Checklist". These forms will be used in the future and be on file. Two of the reviews have already been made and all others will be completed by January 15, 1993.
3. VIOLATION: 10 CFR 39.33(a)(c)(1) requires, in part, that each survey instrument used to conduct physical radiation surveys be calibrated at intervals not to exceed six months and after each instrument servicing.
EXPLANATION & CORRECTIVE ACTION: No excuse for this mistake. We were trying to weed out our older meters and use only our best since we were down sizing our


9301070356 921229
PDR ADOCK 03005849
C PDR

PHONE (216) 264-6560
FAX (216) 263-4080

DEC 7 1992

PHONE (814) 362-1956
FAX (814) 368-8806

operations. Meter 2292 was sent in for calibration and our supervisor thought that it was Meter 2290. We are now using a Calibration & Repair service that notifies us 30 days in advance of due dates. Along with our own chart for calibration due dates, this violation should not happen again. We will continue to stagger our calibration dates so that three up to date meters will be available for use at all times.


Wm. L. Musselman, Pres. & RPO.