

Notice of Violation

Based on the results of NRC inspection conducted on July 7, 8 and 9, 1975, it appears that certain of your activities were not conducted in full compliance with conditions of your NRC License No. SUB-1010 as indicated below:

1. Contrary to License Condition 8 which incorporated the representations, specifications, and procedures in Appendix A of the September 23, 1969, license application, as supplemented on January 14 and February 3, 1970,
 - a. a quarterly audit of the overall health and safety program (as described in Appendix A, p. 11) was not made by the Facility Manager, the Health Physics Officer, and the Licensing and Regulation Officer during the fourth quarter of 1974, and the audits performed in March and June of 1975 were not overall health and safety audits in that most components of the health physics program were not inspected.
 - b. urine samples were not always collected monthly as required by your established routine internal dosimetry program (described in Appendix A, p. 8).

These infractions had the potential for causing or contributing to an occurrence related to health and safety.

2. Contrary to License Condition 11 which incorporates Annex A to Source Material License No. SUB-1010, MSA canisters, model 88182, were used on full face mask respirators without first having been evaluated by the licensee or approved by the U. S. Bureau of Mines, as required by paragraph 1.D. of Annex A.

This infraction had the potential for causing or contributing to an occurrence related to health and safety.

8507310158 850530
PDR FOIA
BURR85-229 PDR