

License No. SUB-1010

Notice of Violation

Based on the results of the NRC inspection conducted on July 28, 29, and 30, 1976, certain activities appear to be in noncompliance with the conditions of your NRC License No. SUB-1010 as indicated below:

Contrary to License Condition 12, the entrance to the plant identified as the construction gate, located in the southwest corner of the restricted area was not posted in accordance with Section 20.203(e)(2) and with the words, "Any area within this plant may contain radioactive material," on July 28, 1976. (The inspector verified that this gate was posted in accordance with the above requirement on July 30, 1976.)

This is an infraction.

8507310239 850530
PDR FOIA
BURR85-229 PDR