



**ROCKY MOUNTAIN
ENERGY**


A Subsidiary of
Union Pacific Corporation

Docket No. 40-8330

PDR

Return to
D-Cramer
396-55

May 6, 1981



Mr. Richard Chancellor
District IV Supervisor
DEQ, Land Quality Division
30 East Grinnell St.
Sheridan, WY 82801

Dear Mr. Chancellor:

RE: TFN 1 5/186 Nine Mile Lake
Patterns 3 and 4 Status Report

Attached are results of the April sampling of the Pattern 3 and 4 monitor wells at Nine Mile Lake. All wells in both patterns are below respective upper control limits for excursion indicator parameters with the exception of uranium in Pattern 3 wells M-40 and M-43.


As noted in my letter of April 27 to you, plans to begin restoration of Pattern 3 are currently being made.

If you have any questions, please give me a call.

Sincerely,

Michael R. Neumann


Michael R. Neumann
Field Environmental Coordinator



MRN/pa

Attachments

cc: Margery Hulburt (LOD)
Tony Mancini (WOD)
Tom Mueller (WOD, District IV)
[REDACTED]
NRC Region IV
R. E. Hynes
R. E. Iwanicki
8.20-4



FILE

24/D3

ISL Development
P.O. Box 3719
Casper, Wyoming 82501
307/237-8326

B106040 097

10059
Add'l info