



**GULF STATES UTILITIES COMPANY**

RIVER BEND STATION

POST OFFICE BOX 220

ST. FRANCISVILLE, LOUISIANA 70775

AREA CODE 504

635-6094


346-8651

June 6, 1985

RBG- 21215

File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011



Dear Mr. Martin:

River Bend Station - Unit 1  
Docket No. 50-458  
Interim Report/DR-304

An interim for final status report concerning a potential wall thickness problem with SA106 pipe supplied by Phoenix Steel will be provided by June 17, 1985.

Sincerely,

*J. E. Booker*

J. E. Booker  
Manager-Engineering,  
Nuclear Fuels & Licensing  
River Bend Nuclear Group

JEB/<sup>PT</sup>PJD/amg

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

NRC Resident Inspector-Site

85-453

8506200029 850606  
PDR ADOCK 05000458  
S PDR

EE-27 1/0