

APPENDIX A

NOTICE OF VIOLATION

Instrument Control Service
Mobile, Alabama 36605

Docket No. 30-20004
License No. 01-20628-01

As a result of the inspection conducted on April 18, 1985, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violations were identified:

Condition 20 of License No. 02-20628-01 requires that licensed material be possessed and used in accordance with statements, representations and procedures contained in application dated July 25, 1983.

1. Item 8.1 of this application requires that survey meters be calibrated on a three month interval from the initial calibration.

Contrary to the above, as of April 18, 1985, the Victoreen model 493 survey meter had not been calibrated since August 29, 1983, a period in excess of three months.

This is a Severity Level IV violation. (Supplement VI)

2. Item 8.1 of this application states that a sufficient number of properly calibrated survey instruments will be available at all times. To ensure this one survey meter will be calibrated in January and one in February.

Contrary to the above, as of April 18, 1985, only one survey meter was available and no provisions have been made to obtain another meter for when the one meter was to be sent for calibration.

This is a Severity Level IV violation. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, Instrument Control Service is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8506200040 850613
REG1 LIC30
01-20628-01 PDR