

DCD/DCB

Bowser-Morner
ATTN: Mr. K. Taylor
Division Director
4518 Taylorsville Road
Huber Heights, OH 45424

License No. 34-19390-01
Docket No. 030-12676

DEC 24 1992

Dear Mr. Taylor:

This refers to the routine safety inspection conducted by Ms. T. L. Simmons of this office on November 20, 1992, of activities authorized by NRC Byproduct Material License No. 34-19390-01, and to the discussion of our findings with you and Mr. D. Ream at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities were found to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosure, and your response to this letter will be placed in the NRC Public Document Room.

The response directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

B. J. Holt, Chief
Nuclear Materials Inspection
Section 1

Enclosure: Notice
of Violation

cc w/enclosure:
DCD/DCB (RIDS)

070010

RIII
Simmons/jaw
12/11

RIII
Holt
12/24/92

9301080101 921224
PDR ADOCK 03012676
C PDR

IE 07