


35 MAY 7 4 9:56



Dr. J. Nelson Grace
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta St., N.W.
Suite 2900
Atlanta, GA 30323

Dear Dr. Grace:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
IE Inspection Reports 250-84-28 and 251-84-29
Supplemental Response

Our supplemental response (L-85-26, dated January 17, 1985) to the subject Inspection Report stated that should a new completion date be required for the incorporation of a software routine for a DDPS poison report, we should notify you accordingly (see Finding 2a, Response 5d).

Due to availability and operability problems on the computer system used to develop software routine changes for the DDPS, we must reschedule completion of that item to January 1, 1986.

Very truly yours,

J. W. Williams, Jr.
Group Vice President
Nuclear Energy

JWW/SAV/js

cc: Harold F. Reis, Esquire
PNS-LI-85-170

8506200367 850430
PDR ADDCK 05000250
Q PDR

1/0
IE 01