



OFFICE OF THE  
SECRETARY

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D.C. 20555

December 18, 1992

RELEASED TO THE PDR

1/7/93

date

initials

MEMORANDUM FOR: James M. Taylor  
Executive Director for Operations

FROM: Samuel J. Chilk, Secretary

SUBJECT: SECY-92-377 - MAINTENANCE INSPECTION GUIDANCE  
PROCEDURE IP 62703

This is to advise you that the Commission (with all Commissioners agreeing) has not objected to the issuance of inspection procedure IP 62703 for use during the interim period from the present until the effective date of the new maintenance rule, 10 CFR 50.65 (July 10, 1996), with the following addition. The following should be added to the end of the paragraph on Troubleshooting Activities in Section 62703-03:

A licensee is expected to have general procedures to control troubleshooting activities such as removal and return of equipment to service, use of lifted leads and jumpers, and post activity testing. While a licensee should have a procedure that addresses the general plan of the troubleshooting activity, it is not always necessary that all of the steps performed as part of a troubleshooting activity be defined in a step-by-step procedure.

(EDO)

(SECY Suspense: 12/31/92)

The staff should move forward on a more expeditious schedule to develop inspection procedures for use in conjunction with the final rule. Since some licensees may wish to begin implementing the new rule before July of 1996, the staff should recommend a course of action which would provide for an initial draft inspection procedure concurrent with the finalization of the implementing guidance for the maintenance rule to be followed by adoption of final inspection procedures prior to January of 1996.

(EDO)

(SECY Suspense: 2/26/93)

080060

SECY NOTE: THIS SRM AND SECY-92-377 WILL BE MADE PUBLICLY  
AVAILABLE 10 WORKING DAYS FROM THE DATE OF THIS  
SRM

9301110248 921218  
PDR 10CER  
PT9.7 PDR

DF02 1/10

Commissioner Curtiss additionally requests that the staff provide recommendations to the Commission on whether and, if so, how NRC might make use of the joint Task Force that was responsible for implementing the Maintenance Rule in the development of the inspection guidance.

cc: The Chairman  
Commissioner Rogers  
Commissioner Curtiss  
Commissioner Remick  
Commissioner de Planque  
OGC  
OIG  
Office Directors, Regions, ACRS, ACNW (via E-Mail)  
OP, SDBU/CR, ASLBP (via FAX)