

OCT 24 1983

FCML:JH

William H. Rorer, Inc
ATTN: Andrew Polk
Radiation Safety Officer
500 Virginia Drive
Fort Washington, PA 19034

Docket No. 030-06195
License No. 37-08802-01
Control No. 01760

SUBJECT: LICENSE RENEWAL APPLICATION

Gentlemen:

This is to acknowledge receipt of your application for renewal of the material(s) license identified above. Your application is deemed timely filed, and accordingly, the license will not expire until final action has been taken by this office.

Any correspondence regarding the renewal application should reference the control number specified and your license number.

Sincerely,

John W. Hickey

Material Licensing Branch
Division of Fuel Cycle and
Material Safety

JBC
10/21/83

"OFFICIAL RECORD COPY"

8505280514 850506
REG1 LIC30
37-08802-01 PDR

ML10

BETWEEN: William O. Miller, Chief
License Fee Management Branch
Office of Administration

John E. Glenn, Chief
Nuclear Materials Section B
Division of Engineering and
Technical Programs

LICENSE FEE TRANSMITTAL

A. REGION

1. APPLICATION ATTACHED

Applicant/Licensee:

William H. Rorer, Inc.

Application Dated:

9-19-83

Control No.:

01760

License No.:

37-08802-01

2. FEE ATTACHED

Amount:

\$460.00

Check No.:

221497

030-06195

3. COMMENTS

Distribution
Headquarters
inc.

Signed

Sharon Johnson

Date

9-23-83

B. LICENSE FEE MANAGEMENT BRANCH

1. Fee Category and Amount:

3A - \$460

2. Correct Fee Paid. Application may be processed for:

Amendment

Renewal

License

✓

Signed

Allen S. Cabell

Date

10/5/83

CONVERSATION RECORD

TIME

DATE

10/27

TYPE

☐ VISIT

☐ CONFERENCE

☐ TELEPHONE

☐ INCOMING

☐ OUTGOING

Location of Visit/Conference:

NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU

H Jack

ORGANIZATION (Office, dept., bureau, etc.)

Com H Rouse

TELEPHONE NO.

SUBJECT

ROUTING

NAME/SYMBOL INT

SUMMARY

We are to remove the model 910 Chromatograph from his appl for removal. This ^(the 910 Chromatograph) cannot accept the Di 63 + has been without a source for quite some time. He verified that the plant (that has been with him a long time) ^{that the was turned in} and where by he could spend alot of time researching old records there + come up with them - He asked if this is what he should do. I mentioned I would document this in his pending removal file + if when being reviewed it was desired, he would be contacted -

Otherwise the H P + 900 Blekin Elmer are only 2 gas Chroms to be listed

ACTION REQUIRED

"OFFICIAL RECORD COPY"

ML10

NAME OF PERSON DOCUMENTING CONVERSATION

SIGNATURE

J Mather

DATE

10/28

ACTION TAKEN

SIGNATURE

TITLE

DATE

CONVERSATION RECORD

TIME

DATE

10/25/83

TYPE

☐ VISIT

☐ CONFERENCE

☒ TELEPHONE

☐ INCOMING

☒ OUTGOING

ROUTING

NAME/SYMBOL

INT

Location of Visit/Conference:

NAME OF PERSON(S) CONTACTED OR IN CONTACT
WITH YOU

Mr. Polk

ORGANIZATION (Office, dept., bureau,
etc.)

Wm H Rorer, Inc.

TELEPHONE NO.

SUBJECT

Control 01760 re: Renewal of 37-08802-01

SUMMARY

Regarding Item 8, subitem 10 (gas chromatographs) applied for on application

dated 9/19/83 for renewal of license:

(a) Should read: Hewlett/Packard Model 2-6195 (instead of #7620A)

(b) should read: Perkin Elmer 910 Model No. (10 mci) - He said that this
was a typo on his application

(c) Perkin Elmer 900 Model No - 15 mci - is correct

These Perkin Elmer Models (910 & 900) were purchased early 1970's and are
not on our inactive catalogue sheets. He called Perkin Elmer and verified that
these model nos are correct. He continues to be authorized a spare 15 mci Nickel
source even though it is not on hand. This was previously authorized for him
by J. Jones. He is well aware that if he receives new equipment he will need
to come in with an amendment to his license stating the model no. applied for.
Therefore, this is the reason for the authorization of 42 mci of Nickel 63 on
this present renewal.

"OFFICIAL RECORD COPY"

ACTION REQUIRED

ML10

NAME OF PERSON DOCUMENTING CONVERSATION

IC Martin

SIGNATURE

IC Martin

DATE

10/25/83

ACTION TAKEN

SIGNATURE

TITLE

DATE