

License: 35-23436-01  
Docket: 30-21074

5-6-85

United Inspection, Inc.  
ATTN: Ernie Busby, President  
6700-A New Sapulpa Road  
Tulsa, Oklahoma 74013

Gentlemen:


Thank you for your letter of April 9, 1984, in response to our letter and the attached Notice of Violation and Proposed Imposition of Civil Penalty dated March 1, 1985. As a result of our review, we find additional information, as discussed with you during a telephone call on April 23, 1985, is needed. Specifically, for Violations 1, 2, 4, and 5, your corrective steps that will be taken to avoid further violations, and for Violation 5, the date when full compliance will be achieved. In addition, the response must be submitted under oath or affirmation.

Please provide the supplemental information within 10 days of your receipt of this letter so that we can continue our review of this matter.

Sincerely,

Original Signed by:

2015 Check



Robert D. Martin  
Regional Administrator

cc:  
Oklahoma Dept. of Health

DISTRIBUTION W/LETTER DATED 4/9/85:

PDR

SECY

CA

JMTaylor, IE

RVollmer, IE

JAxelrad, IE

JLieberman, ELD

LCobb, IE

FIngram, PA

DChappel, NMSS

VMiller, NMSS

JCrooks, AEOD

BHayes, OI

SConnelly, OIA

DNussbaumer, OSP

Enforcement Coordinators

RI, RII, RIII, RIV, RV

IE:ES File (ltr hd)

IE:EA File (ltr hd)

BSummers, IE (ltr hd)

DCS

RIV Distribution:

Regional Administrator, RMartin

RBangart

JEverett

Inspector

CWisner (ltr hd)

NMS&SB (w/ltr hd)

RIV Files

8505290121 850506  
REG4 LIC30  
35-23436-01 PDR

RIV:NMSS  
CHooker sm

4/30/85

NMSS  
JEverett

4/30/85

NMS&SB  
JEverett

4/30/85

DR&S  
RBangart

4/30/85

EO  
TWesterman RMartin


5/1/85

2/28/85



# UNITED INSPECTION INC.

6700-A NEW SAPULPA ROAD  
TULSA, OKLAHOMA 74131



U.S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

April 9, 1985

Gentlemen:

In reply to your letter of violation and proposed penalty I would like to state that the incidents for which I was cited showed that I was not as thorough as I should have been and I feel that the proposed penalty was justified.

There is no excuse as I indicated to you in our meeting in Arlington, and we will continue to do everything we can to see to it that these problems or other ones do not arise again. Also we are going to do all that we can do to erase whatever effect it may have had on your attitude towards our company.

The following has been done to insure that we are in compliance:  
#1. Sources are no longer being stored at facility at 5500 E. Independence, Tulsa, Oklahoma, until we can get that storage facility on our license.

#2. The facility at 5500 E. Independence has been appropriately reconstructed to comply with 10 CFR 20.105 (b)(1.).

#3 All employees have been strictly reminded of the requirements of 10 CFR 20.201 (b). and are randomly spot checked for compliance.

#4 Shortly after our inspection our facility at 5500 E. Independence was equipped with lights and warning devices to bring it into compliance with 10 CFR 34.29 (b).

#5 All radiographers have now availability to dosimeter chargers if they do not come in to the office every day whether in is in a vehicle or at a permanent job site. This to comply with 10 CFR 34.33(a).

#6 All new employees regardless of previous experience are given a field competency exam by the Radiation Safety Officer **before** being given a job assignment and records are maintained to document this.

United INspection Inc.

*Ernie C. Lusby*  
Radiation Safety Officer

*DR 8504/170165*

*LC-024/85*