

DMB COPY

JUL 1 - 1985

Hurley Medical Center
ATTN: Mr. Jack Dagenais
Assistant Director
One Hurley Plaza
Flint, MI 48502

Licenses No. 21-00338-02;
SNM-1393

Gentlemen:

This refers to the routine safety inspection conducted by Mr. W. P. Reichhold of this office on May 2, 3, and 24, 1985, of activities authorized by NRC Byproduct Material Licenses No. 21-00338-02 and Special Nuclear Material License 1393, and to the discussion of our findings with you on May 24, 1985. The results of the inspection were discussed on June 7, 1985, during an enforcement conference in the Region III office between you and me and others of the NRC staff.


The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The enclosed copy of our inspection report identifies the items examined during the inspection which consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection certain of your activities appeared to be in noncompliance with NRC requirements. You will be notified by separate correspondence of our decision regarding enforcement actions based on the findings of this inspection. No written response is required until you are notified of the proposed enforcement action.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

8507050190 850701
REG3 LIC70
SNM-1393 PDR


J. R. Hind, Director
Division of Radiation Safety
and Safeguards

Enclosure: Inspection Reports
No. 030-01993/85001(DRSS);
No. 070-01396/85001(DRSS)

cc w/enclosure:
DMB/Document Control Desk (RIDS)

RIII
Reichhold/jp
06/17/85

RIII
Sreniawski
6/21

RIII
Axelson
6/21

RIII
Stapleton

RIII
Hind
6/28/85

IED7
11