

NRC Form 591  
(12-81)  
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

## SAFETY INSPECTION

## 1. LICENSEE

Department of the Interior  
Bureau of Land Management  
Arizona State Office  
2400 Valley Bank Center  
Phoenix, Arizona 85073

## 2. REGIONAL OFFICE

U. S. Nuclear Regulatory Commission  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, CA 94596

## 3. DOCKET NUMBER(S)

030-12367

## 4. LICENSE NUMBER(S)

02-17208-01

## 5. DATE OF INSPECTION

April 16, 1985

## Licensee:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission's (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews, with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- ☐ 1. Within the scope of this inspection, no violations were observed.
- ☐ 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- ☒ 3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements.  
**THIS IS A NOTICE OF VIOLATION** which is required to be posted in accordance with 10 CFR 19.11.
- ☐ A. \_\_\_\_\_ was not properly posted to indicate the presence of a \_\_\_\_\_ 10 CFR 20.203(b), (c), (d), (e) or 34.42.
- ☐ B. Containers located in \_\_\_\_\_ were not properly labeled to indicate the presence of radioactive material. 10 CFR 20.203(f)(1), or (f)(2).
- ☒ C. Physical inventories \_\_\_\_\_ of sealed sources were not performed at the proper frequencies. 10 CFR \_\_\_\_\_ License Condition Number 15
- ☒ D. Records of leak tests of the sealed source in gauge S/N M19113009 were not properly maintained. 10 CFR \_\_\_\_\_ or License Condition Number 14
- ☒ E. Documents were not properly posted or otherwise made available. 10 CFR 19.11. (a), (c)
- ☐ F. Reports or notifications of \_\_\_\_\_ were not made in accordance with 10 CFR \_\_\_\_\_ or License Condition Number \_\_\_\_\_
- ☒ H. Contrary to License Condition 10, licensed material was relocated to a new permanent address 34 Yuma, Arizona without properly amending the license to authorize the new use location. Also, the licensee's main office was relocated to a new permanent address of 3707 N. 7th Street, Phoenix, Arizona without proper amendment of
- ☐ I. License Condition 2.
- ☐ J. \_\_\_\_\_
- ☐ K. \_\_\_\_\_

8505290280 850523  
REGS LIC30  
02-17208-01 PDR

I hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

*David Ball*

*5/3/85*

*David G. Krow*

*4/24/85*