



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

May 20, 1985

RBG-

File Nos. G9.5, G9.8.6.2

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U.S Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Denton:

River Bend Station - Unit 1
Docket No. 50-458

Pursuant to your request for a schedule for submittal of information, Gulf States Utilities has listed the items which were identified as OPEN/CONFIRMATORY ITEMS AWAITING INFORMATION and provided either a reference for our submittal which provided the information or a scheduled date for the submittal of that information. This completes our response to Mr. A. Schwencer's Request for Additional Information dated May 3, 1985 (RBC-31,987).

Sincerely,

J. E. Booker

J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

erg
JEB/ERG/je

Attachment

*✓3001
11*

8505290429 850520
PDR ADOCK 05000458
A PDR

ISSUES STATUS
FROM NRC 5-3-85 LETTER

| <u>Type</u> | <u>Abbr. Title</u> | <u>Response/Schedule</u> | |
|-------------|------------------------|--------------------------|----------------|
| OI.05 | Equipment Qualifctn | 05/15/85 | RBG-20,996&7&8 |
| OIN.21 | Enviro Qualification | 04/26/85 | RBG-20,811 |
| CI.04 | Pipe fail/chk valve | 05/20/85 | RBG-21,042 |
| CI.07 | Thermal/anchor loads | 12/21/84 | RBG-19,755 |
| OI.04 | Inservice Test Program | 05/16/85 | RBG-21,019 |
| OI.13 | Safe/alt. shutdown | 05/17/85 | RBG-21,036 |
| CI.01 | W. Creek sedmnt rmovl | 05/13/85 | RBG-20,959 |
| OI.06 | Preserv Inspect Prog | 05/15/85 | RBG-20,992 |
| OIN.22 | SPDS | 05/15/85 | RBG-21,018 |
| CI.60 | TMI Item I.C.1 | 05/15/85 | RBG-21,017 |
| CIN.66 | Particp in DCRD rev | 05/14/85 | RBG-20,973 |
| CIN.67 | Task Anal document | 05/14/85 | RBG-20,973 |
| CIN.67 | Control room mods | 05/14/85 | RBG-20,973 |
| OIN.24 | Control room survey | 05/14/85 | RBG-20,973 |
| OIN.25 | Resolution of HEDs | 05/14/85 | RBG-20,973 |
| OI.03 | Hi-energy line brks | 05/31/85 | |
| OIN.23 | Standby serv water | 05/14/85 | RBG-20,974 |
| CI.47 | Elect distrib system | 05/31/85 | * |
| OI.10 | Diesel Generators-Load | 05/16/85 | RBG-20,993 |
| OIN.19 | Separatn-elec circ. | 05/02/85 | RBG-20,931 |
| CI.12 | Reactr vessl cooldwn | 05/15/85 | Telecon |
| CI.14 | Mark III issues | 03/01/85 | RBG-20,270 |
| CI.16 | Inleakage limit | 05/06/85 | RBG-20,903 |
| CI.19 | Hydrogen control | 05/31/85 | * |
| CI.20 | PVLCs leakage | 05/06/86 | RBG-20,903 |
| OI.07 | Containment Loads | 05/29/85 | * |
| CI.18 | Contain purge valves | 05/13/85 | RBG-21,037 |
| CI.26 | Isolation devices | 04/02/85 | RBG-20,595 |
| CI.29 | ESF reset control | 05/31/85 | * |
| CI.40 | DRMS | 05/10/85 | RBG-20,944&5 |
| CI.57 | License operator rev | 03/07/85 | RBG-20,350 |
| CI.62 | Proper ESF function | 05/31/85 | |
| CI.63 | Safety system operab | 05/17/85 | IEIR 85-38 |

* Not required for low power license as per 5-3-85 letter and discussions with your Staff.