



MERCY HOSPITAL

11/22-DCS

800 MERCY DRIVE

COUNCIL BLUFFS IOWA 51501

September 17, 1980

U.S. Nuclear Regulatory Commission
Regein III
799 Roosevelt Road
Glen Ellyn, IL 60137

Attention: Samuel L. Pettijohn
Material Licensing Branch

Dear Mr. Pettijohn:

This letter of response pertains to your request for additional information dated July 31, 1980, and otherwise known as Mail Control No. 03443.

1. Attached please find a sketch of the connection of the effluent tubing from the Xenon Delivery System to the venting effluent duct of the air handling unit. The connection will consist of an aluminum boot which has been installed around a 3 inch circular hole but in the underside of the effluent duct, approximately 18 inches or the negative pressure side of vent #11 (please refer to the engineering sketch of the air handling system which accompanied the May 5, 1980, application for amendment of License 14-13474-01).
2. This item was resolved as a result of your telecommunication with Thomas F. Young on August 20, 1980, in which you indicated that no further explanation is necessary.

Thank you for your expeditious review of these matters.

Yours truly,

J. C. Tanous, M.D.

Enclosure

8505300542 850329
REG3 LIC30
14-13474-01 PDR

SEP 19 1980

MERCY HOSPITAL, COUNCIL BLUFFS, IOWA

SKETCH -- INSTALLATION OF XENON-133 GAS VENTILATION DUCT

