


UNITED STATES ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

File
11/15/61

1. LICENSEE The Carborundum Company The Carborundum Metals Company Div. P. O. Box 32 Akron, New York		2. REGIONAL OFFICE OAK RIDGE COMPLIANCE AREA DIVISION OF COMPLIANCE, USAEC P. O. BOX 8 OAK RIDGE, TENNESSEE	
3. LICENSE NUMBER(S) STN-440 (Docket No. 40-3001)			
4. INSPECTION FINDINGS			
		Date of inspection <u>11-15-61</u>	
<input checked="" type="checkbox"/> A. No item of noncompliance was found.			
<input type="checkbox"/> B. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b)			
<input type="checkbox"/> C. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c)(1)			
<input type="checkbox"/> D. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)			
<input type="checkbox"/> E. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)			
<input type="checkbox"/> F. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f)(1) or (f)(2)			
<input type="checkbox"/> G. Storage containers were not properly labeled to show the quantity, date of measurement, or kind of radioactive material in the containers. 10 CFR 20.203(f)(4)			
<input type="checkbox"/> H. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)			
<input type="checkbox"/> I. Form AEC-3 was not properly posted. 10 CFR 20.206(c)			
<input type="checkbox"/> J. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(e)			
<input type="checkbox"/> K. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b)			
<input type="checkbox"/> L. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.41, 40.61 or 70.51			
<input type="checkbox"/> M. Records of leak tests were not maintained as prescribed in your license.			
<div style="text-align: right;"> AEC Representative</div>			
5. LICENSEE'S ACKNOWLEDGMENT The AEC representative has explained and I understand the items of noncompliance listed above, if any. The items of noncompliance will be corrected within the next 30 days.			
Date _____		Licensee Representative _____	

COPIES: ☐ LICENSEE; ☐ COMPLIANCE AREA; ☒ DIV. OF LIC. & REG.; ☐ DIV. OF COMPLIANCE (2)

GPO 510402

2/17/89

33
A/