

CONSULTANTS
GEOLOGY
ENGINEERING
DRAFTING

RILEY, MANNON, & STURGEON, LTD.

(304)
522-8328

May 8, 1985

Mr. John Potter
U.S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W.
Atlanta, Ga. 30323

85 MAY 13 AM 10:59


Mr. Potter:

As per your telephone conversation on May 8, 1985, with Mr. Pat Riley, in reference to Mr. L. Franklin's Report No. 47-19672-01/85-01, dated April 30, 1985, for insufficient survey meter calibration between the dates of February 17, 1982 and July 12, 1983, please find enclosed copies of the calibration report for the time period in question.

This record was evidently mis-filed and therefore was not available for inspection on the violation date cited above.

Your co-operation in this matter is greatly appreciated. If there are any questions concerning this matter please advise.

Sincerely,



William L. Adkins
Vice-President, Adm.

Encl:3
WLA/bn

Official Copy

SUITE 1410

WEST VIRGINIA BUILDING

HUNTINGTON, W. VA. 25701

8507100204 850611
REQ2 LIC30
47-19672-01 PDR