

May 9, 1985

Docket No. 50-368

Mr. John M. Griffin, Senior Vice President
Energy Supply
Arkansas Power & Light Company
P. O. Box 551
Little Rock, Arkansas 72203

Dear Mr. Griffin:

DISTRIBUTION:

~~DOCKET FILE~~

NRC PDR
Local PDR
ORB#3 Rdg
HThompson
OELD
EJordan
BGrimes
JPartlow
RSLee
PMKreutzer

Gray File
ACRS +10
GLear/SGEB

By letter dated May 30, 1984, you submitted a 5 year tendon surveillance report for ANO-2 Reactor Containment Building. Based on our review of the report, we have determined that the 5 year tendon surveillance was performed in accordance with the regulatory requirements and the tendons met the requirements imposed by the reference standards and the NRC staff requirements. Our Safety Evaluation (SE) is enclosed.

With respect to our evaluation concerning indications of filler material leakage, we expect you to review the information in the SE and consider actions, if appropriate, to preclude similar problems in the future. However, suggestions contained in the SE do not constitute NRC requirements; therefore, no specific action or written response is required. If you decide to take further action in this matter, it is requested that you advise us by response to this letter.

Sincerely,

James R. Miller, Chief
Operating Reactors Branch #3
Division of Licensing

Enclosure:
Safety Evaluation

cc w/enclosure
See next page

8505300654 850509
PDR ADOCK 05000368
P PDR

ORB#3:DL
PMKreutzer
5/8/85

ORB#3:DL
RSLee:dd
5/8/85

SGEB/DE
GLear:dd
5/8/85

ORB#3:DL
JRMiller
5/8/85

Changes were discussed with and agreed to by Glear on 5/8/85
Bob Lee