



JUN 5 1970

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

<p>1. LICENSEE AMAX Specialty Metals, Incorporated P. O. Box 1748 Parkersburg, West Virginia 26101</p>	<p>2. REGIONAL OFFICE U. S. Atomic Energy Commission Region II, Divn. of Compliance 230 Peachtree Street, NW - Suite 818 Atlanta, Georgia</p>
<p>3. LICENSE NUMBER(S) STB-440 (Docket No. 40-5001)</p>	<p>4. DATE OF INSPECTION May 28, 1970</p>
<p>5. INSPECTION FINDINGS</p> <ul style="list-style-type: none"> <input type="checkbox"/> A. No item of noncompliance was found. <input type="checkbox"/> B. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.42 <input type="checkbox"/> C. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42 <input type="checkbox"/> D. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d) <input type="checkbox"/> E. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e) <input type="checkbox"/> F. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2) <input type="checkbox"/> G. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b) <input type="checkbox"/> H. Form AEC-3 was not properly posted. 10 CFR 20.206(c) <input type="checkbox"/> I. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b) <input checked="" type="checkbox"/> J. Records of surveys or disposals were not properly maintained. <u>10 CFR 20.401(b) or 34.43(d)</u> <input type="checkbox"/> K. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51 <input type="checkbox"/> L. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c) <input type="checkbox"/> M. Records of inventories were not maintained. 10 CFR 34.26 <input type="checkbox"/> N. Utilization logs were not maintained. 10 CFR 34.27 	
<p style="text-align: right;">  (AEC Compliance Inspector) </p>	
<p>6. LICENSEE'S ACKNOWLEDGMENT</p> <p>The AEC Compliance Inspector has explained and I understand the items of noncompliance listed above. The items of noncompliance will be corrected within the next 30 days.</p> <div style="display: flex; justify-content: space-between; margin-top: 20px;"> <div style="text-align: center;"> <p><u>6/10/70</u> (Date)</p> </div> <div style="text-align: center;"> <p> (Licensee Representative - Title or Position)</p> </div> </div>	

ORIGINAL: LICENSEE. COPIES: ☐ CO REGION ☒ CO HEADQUARTERS ☐ CO ENFORCEMENT

9302170295 921007
PDR FOIA
KEPPLER92-446 PDR

2/17/295 A/52

INVOICE FOR FACILITIES AND MATERIALS LICENSES

UNITED STATES ATOMIC ENERGY COMMISSION

CENTRAL ACCOUNTS BRANCH

WASHINGTON, D. C. 20545

TO:

AMAX SPECIALTY METALS, INCORPORATED P.
U. BOX 1748

PARKERSBURG

WVA 26101

NO.

L-0100-71

DATE:

FEB. 5, 1971

TERMS:

NET 30 DAYS

LICENSE NO. 47-12653-01

CATEGORY OF LICENSE	FEE FOR FACILITIES AND MATERIALS LICENSES PURSUANT TO 10 CFR 170	AMOUNT
5A	ALL OTHER SPECIFIC MATERIALS LICENSES.	40.0
ANNUAL FEE FOR THE PERIOD 02/05/71 - 02/04/72 AMOUNT DUE →		40.0

MAKE CHECK PAYABLE TO U. S. ATOMIC ENERGY COMMISSION AND MAIL TO ABOVE ADDRESS WITH ENCLOSED CARD. PLEASE RETAIN INVOICE FOR YOUR RECORDS. PAYMENT OF THIS FEE DOES NOT CONSTITUTE APPLICATION FOR RENEWAL OF YOUR LICENSE PURSUANT TO THE COMMISSION'S REGULATIONS.

AL 53