

ENCLOSURE 1

NOTICE OF VIOLATION

Florida Power Corporation
Crystal River Unit 3

Docket No. 50-302
License No. DPR-72

The following violations were identified during an inspection conducted on April 26 - May 24, 1985. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 6.8.3 allows temporary changes to be made to surveillance procedures provided that the intent of the original procedure is not altered and that the change is approved by two members of the plant manager staff, at least one of whom holds a Senior Reactor Operators (SRO) license.

Contrary to the above, on May 14, 1985, a temporary change was made to surveillance procedure SP-354A (Emergency Diesel Fuel Oil Quality and Diesel Generator Monthly Test) and the change was not approved by two members of the plant management staff, at least one of whom holds a SRO license.

This violation is similar to a violation identified in NRC Inspection Report 50-302/85-08 dated April 11, 1985, and a violation discussed (but not cited) in NRC Inspection Report 50-302/85-11 dated April 23, 1985.

This is a Severity Level IV violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

It is recognized that the above cited violation has been addressed, as required, in your June 6, 1985, response to our Notice of Violation dated April 11, 1985, regarding the similar violation 50-302/85-08-07. We are presently evaluating this response, therefore, no additional response to the above cited violation is required.

JUN 21 1985

Date: _____

8507100545 850621
PDR ADOCK 05000302
Q PDR