

LAUREL DIAGNOSTIC CENTER, INC.

LAUREL PROFESSIONAL BUILDING
109 EAST LAUREL ROAD
STRATFORD, N. J. 08084

627-8844

May 7, 1985

United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA 19406

RE: Docket No. 030-20592

Gentlemen:

This is in answer to your letter dated April 19, 1985 relating to an inspection of our facility on March 28th, 1985 by Ms. Judith A. Joustra. Two points in your letter require response, and these are dealt with in order:

(1) Appendix A - Notice of Violation, Item 1

A dose calibratory linearity test was performed the week following the inspector's visit (April 1st through 4th). Our consultant physicist analyzed the data taken by technologist and his report indicated no deficiencies in dose calibrator linearity.


A tickler file has been created in which this, and other periodic requirements, are listed. Our regular reference to this file should assure that the quarterly linearity test will not be neglected in the future.

We feel we are currently in compliance, with performance of this test. However, you may not feel that efficacy of our program change is fully proven until we are properly reminded of the next quarterly dose calibrator linearity test in early July, 1985.

- (2) Your understanding is correct that we will shortly be applying for an amendment changing, among other things, the name on the license. We feel it will be more appropriate to have the license in the name of the organization in which the nuclear medicine imaging is performed rather than in that of an individual, although it is intended that several individual users be named thereon.

8505310227 850524
REG1 LIC30
29-21382-01 PDR

Sincerely,



B. A. Hollander, M.D.

BAH:jh