

GPU Nuclear Corporation
Post Office Box 388
Route 9 South
Forked River, New Jersey 08731-0388
609 971-4000
Writer's Direct Dial Number:

February 10, 1993

C321-93-2051


U. S. Nuclear Regulatory Commission
Att: Document Control Desk
Washington, DC 20555

Dear Sir:

Subject: Oyster Creek Nuclear Generating Station
Docket No. 50-219
Response to NRC Bulletin 90-01, Supplement 1
Loss of Fill Oil in Transmitters Manufactured by Rosemount

On December 22, 1992, the USNRC issued Supplement 1 to NRC Bulletin 90-01. Page 12 of that supplement contained three reporting requirements relating to the suspect lots of Rosemount transmitter. There are no Rosemount model 1153/1154 transmitters from the suspect lots (manufactured before July 11, 1989) installed in any Safety Related or ATWS applications at the Oyster Creek Nuclear Generating Station.

If any additional information or assistance is required, please contact Mr. John Rogers at 609.971.4893.



John J. Barton
Vice President and Director
Oyster Creek

JJB/JJR

cc: Administrator, Region I
Senior Resident Inspector
Oyster Creek NRC Project Manager

9302190136 930210
PDR ADOCK 05000219
Q PDR

JE39/10