

**JOHN E. STROBECK, M.D., Ph.D., P.A.**

One West Ridgewood Avenue  
Suite #302  
Paramus, New Jersey 07652

030-3422

*Diplomate of the American Board of Internal Medicine  
Subspecialty of Cardiovascular Disease  
Interventional Cardiology*

Tel: (201) 652-0088  
Fax: (201) 652-6591

September 24, 1996

Ms. Michelle Beardsley  
License Reviewer  
Nuclear Materials Safety Branch  
Division of Radiation Safety and Safeguards  
U.S. Nuclear Regulatory Commission, Region I  
475 Allendale Road  
King of Prussia, PA 19406-1415

RE: New License Application  
Request For Additional Information  
Control Number: 123576

Dear Ms. Beardsley:

Pursuant to your conversation with Michael W. Lairmore, the following responses are submitted for your examination;

1. We confirm the Heart-Lung Center PA is a non-institution providing diagnostic imaging services. Nuclear medicine operations have been identified on the facility diagram incorporated within the license application. Please refer this document for details.
2. In regards to Teresa A. Lairmore, an outdated copy of the byproduct material license was submitted with our request. Ms. Lairmore has been the radiation safety officer at Holy Name Hospital for the past three years. Please refer to license number 29-03382-01 for additional information.
3. { We confirm that Iodine-131 will not be used at this facility for diagnostic and/or therapeutic purposes. Therefore, a "Quality Management Program" will not be required. }
4. We confirm a back-up survey meter will be made available, when the department's meter is sent for calibration and/or repair.
5. Administrative personnel intends to began nuclear medicine operations at this facility effective October 1, 1996.

150128  
9610150229 960724  
PDR ADOCK 03003422  
C PDR

**ML 11**


OCT - 1 1996

6. At the present time, please delete our request to add John E. Strobeck, M.D. and Robert Bakdajian, M.D. as authorized user(s) on our byproduct material license.

We hope these responses meet with your approval. If you require additional information, please contact Michael W. Lairmore or myself. Mr. Lairmore may be reached at (201) 447-3303.

We thank you for your assistance with this license application.

Sincerely,



John E. Strobeck, M.D.  
President