



Southern Nuclear Operating Company

the southern electric system

10CFR50.55a(g)
10CFR50.36

February 16, 1993

Docket No. 50-348

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

Joseph M. Farley Nuclear Plant - Unit 1
Interval 2/Period 2/Outage 1
Inservice Inspection Report

Gentlemen:

Pursuant to the requirements of 10CFR50.55a(g) and 10CFR50.36, Southern Nuclear Operating Company herewith submits Joseph M. Farley Nuclear Plant Unit 1 Interval 2/Period 2/Outage 1 Inservice Inspection Report. This report describes and summarizes the inservice inspection activities performed during the Unit 1 eleventh refueling outage. These activities were completed November 29, 1992.

Included in this report are the results of the steam generator eddy current testing conducted during this outage as required by 10CFR50.55a(g) and Section 4.4.6.5.b of the Farley Nuclear Plant Unit 1 Technical Specifications. Specifically, the results and a summary may be found in Tab B. None of the information in this report is proprietary and may be reproduced as necessary under government regulations associated with public information rights.

Other pertinent report information is available at Farley Nuclear Plant for your review. This information includes as applicable, examination plans and schedules, examination results and reports, examination methods and procedures, evaluation of results, and corrective actions and repairs.

If there are any questions, please advise.

Respectfully submitted,

190041

J. D. Woodard

JDW/CDP:pgr cdp-oa

Enclosure

cc: Mr. S. D. Ebner
Mr. S. T. Hoffman
Mr. G. F. Maxwell

w/1 encl.

9302220324 930216
PDR ADOCK 05000348
G PDR

*Rec'd
w/out Encl
A047
1/0*