



**RLS & Company**  
**GEOTECHNICAL CONSULTANTS**

3133 Lee Highway  
Abingdon, Virginia 24210

Telephone 703-628-2482

February 18, 1993

**COPY**

Nuclear Regulatory Commission  
Region II  
101 Marietta Street, N.W.  
Atlanta, Georgia 30323

Attn: Regional Administrator

NOTICE OF VIOLATION  
NRC Inspection Report No. 45-24905-01/93-01  
Docket No. 030-29949  
License No. 45-24905-01

Gentlemen:

This is a response to your Notice of Violation dated January 21, 1993.

Our violation dealt with non-compliance with Condition 14 of license 45-24905-01, in part, that the sources specified in item 7, be tested for leakage and/or contamination at intervals not to exceed 6 months. We regret missing the interval, but feel that we have implemented corrective procedures that will keep us in compliance in the future. Mainly, we have posted when the last leak test was done and when the next one is due. Our technicians have access to this posting. Also, we have noted the testing dates in our daily planners. Since the inspection, we have performed a leak test on our Troxler 3430, SN 19741. This gauge is the only one being used this winter. We have ordered leak test refills and on arrival we plan to test both of our Troxler machines so they are on the same testing schedule. The refills should be in next week and we feel we will be in full compliance by February 26, 1993.

Again, we regret our violation and feel we have corrected against future violations.

Sincerely,

Les Sutherland, PE

220102

9302230132 930218  
PDR ADDCK 03029949  
C PDR

507 1/0