

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)

Zion Station, Unit 2

DOCKET NUMBER (2)

0 5 0 0 0 3 0 4 1 OF 0 2

PAGE (3)

TITLE (4)

Missed Boric Acid Transfer Pump Surveillance

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)										
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)								
0	4	2	2	8	5	8	5	0	1	0	0	0	5	0	0	0	0	0	0
THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 8: (Check one or more of the following) (11)																			
OPERATING MODE (9)			20.402(b)			20.405(e)			50.73(a)(2)(iv)			73.71(b)							
POWER LEVEL (10)			20.406(a)(1)(i)			50.38(c)(1)			50.73(a)(2)(v)			73.71(c)							
01 9 9			20.406(a)(1)(ii)			50.38(c)(2)			50.73(a)(2)(vii)			OTHER (Specify in Abstract below and in Text, NRC Form 365A)							
			20.406(a)(1)(iii)			X 50.73(a)(2)(i)			50.73(a)(2)(viii)(A)										
			20.406(a)(1)(iv)			50.73(a)(2)(ii)			50.73(a)(2)(viii)(B)										
			20.406(a)(1)(v)			50.73(a)(2)(iii)			50.73(a)(2)(x)										

LICENSEE CONTACT FOR THIS LER (12)

NAME	TELEPHONE NUMBER
AREA CODE	
Walter J. Sopata	3 1 2 7 4 6 - 2 0 8 4

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC
A				No					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
	X				

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

The required weekly functional test of Boric Acid Transfer pumps was missed, due to an oversight on the part of the Shift Supervisors. To prevent recurrence, the Operating Staff will track required weekly surveillances. A daily review will be made of surveillances due that day, and the Shift Supervisor will be notified of any which are outstanding. No further action is necessary.

8506030624 850522
PDR ADOCK 05000304
S PDR

IE22
11

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Zion Station, Unit 2	05000304	85	-010	-00	02	OF	02

TEXT (If more space is required, use additional NRC Form 366A's) (17)

On 4/22/85, with Unit 2 operating at full power, shift personnel failed to perform surveillance PT-16, "Test of Boric Acid Transfer Pumps." This violated Technical Specification 4.2.1.f.1, which requires the Boric Acid Transfer Pumps to be functionally tested weekly.

Weekly surveillances such as this one are tracked by the shift. A sign-off for weekly completion of PT-16 is contained in PT-0 Appendix G. The Shift Engineer has responsibility to see that daily and weekly required surveillances are performed on time. In this case, PT-16 was missed due to oversight by the shift in filling out and reviewing the shiftly surveillance form.

In calendar 1984, Zion Station reported four missed surveillances by the operating department for units 1 and 2. These are documented in LER's 295/84-025, 295/84-015, 304/84-022 and 304/84-012. This is the first such occurrence in 1985.

In the future, weekly surveillances will be tracked by the operating staff. Each day, the staff will review the list of surveillances due that day. If any surveillances are due and have not been turned in, the Shift Engineer will be notified. This system should prevent required surveillances from being overlooked in the future.



Commonwealth Edison

Zion Generating Station
Shiloh Blvd. & Lake Michigan
Zion, Illinois 60099
Telephone 312/746-2084

May 22, 1985

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Reference: 10CFR50.73

Dear Sir:

The enclosed Licensee Event Report from Zion Generating Station is being transmitted to you in accordance with the requirements of 10CFR 50.73a.2(i) which requires a 30 day written report when there has been an operation or condition prohibited by the plant's Technical Specifications.

This report is number 85-010-00, Docket No. 50-304/DPR-48.

Very truly yours,

for K.L. Graesser
Station Manager
Zion Generating Station

Enclosure: Licensee Event Report No. 85-010-00

Attachment

cc: J.G. Keppler, NRC Region III Administrator
M. Holzmer, NRC Resident Inspector
INPO Record Center
CECO Distribution List

IE22
1/1