

U. S. NUCLEAR REGULATORY COMMISSION

REGION III

Reports No. 50-315/85018(DRSS); 50-316/85019(DRSS)

Docket Nos. 50-315; 50-316 License Nos. DPR-58; DPR-74 Safeguards Group IV

Licensee: American Electric Power Service Corporation  
Indiana and Michigan Electric Company  
1 Riverside Plaza  
Columbus, OH 43216

Facility Name: Donald C. Cook Nuclear Power Plant, Units 1 and 2

Inspection At: Donald C. Cook Site, Bridgman, MI

Inspection Conducted: June 18 and 19, 1985

Date of Last Physical Security Inspection: January 7-11, 1985

Type of Inspection: Special Physical Protection

Inspector: *T. J. Madede*  
Physical Security Inspector

*7/9/85*  
Date

Approved By: *J. R. Creed*  
J. R. Creed, Chief  
Safeguards Section

*7/9/85*  
Date

Inspection Summary:

Inspection on June 18 and 19, 1985 (Report No. 50-315/85018(DRSS); 50-316/85019(DRSS))

Areas Inspected: Included a review of two security events/incidents, pertaining to vital area access control and one event pertaining to reporting an incident to the NRC. The inspection involved 13 inspector hours by one NRC inspector.

Results: Based on inspection findings, two apparent violations were identified.

1. Access Control - Personnel: Licensee failed to adequately control access to a vital area such that on three occasions barriers were degraded and no compensatory measures were taken (Section 4).
2. Records and Reports: Licensee failed to notify the NRC of a reportable physical security event (Section 3).

(Details - UNCLASSIFIED SAFEGUARDS INFORMATION)

Enclosure contains  
SAFEGUARDS INFORMATION  
Upon separation this  
page is Decontrolled

8507150202 850710  
PDR ADOCK 05000315  
Q PDR