



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION IV  
URANIUM RECOVERY FIELD OFFICE  
BOX 25325  
DENVER, COLORADO 80225

DATE:

6/1/83

NOTE TO  
DOCKET FILE:

40-8697

FROM:

Fred Ross

SUBJECT:

REVIEW OF MAIL CONTROL NO. 00304

I have reviewed the subject document and have concluded the following:

- ☐ This document contains information that is not essential to the review and maintenance of this license and no further regulatory review or consideration is warranted.
- ☐ This document contains information that was previously submitted and reviewed and no further action is warranted.
- ☒ This document contains substantive information that is summarized below; however, no further regulatory action is warranted.
- ☐ This document contains substantive information that is summarized below and is essential to the review and maintenance of this license. Further regulatory review or consideration is necessary.

SUMMARY: The WDSQ has determined that Reno  
Creek Pattern II has been restored and  
demonstrates proof of restoration to support  
commercial ops.

DATE DUE TO DOCKET FILE: June 30, 1983