



UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGION IV

URANIUM RECOVERY FIELD OFFICE
BOX 25325
DENVER, COLORADO 80225

DATE:

~~5/23/83~~ 5/23/83

NOTE TO

DOCKET FILE:

40-8697

FROM:

Fred Ross, PM

SUBJECT:

REVIEW OF MAIL CONTROL NO. 00266

I have reviewed the subject document and have concluded the following:

_____ This document contains information that is not essential to the review and maintenance of this license and no further regulatory review or consideration is warranted.

_____ This document contains information that was previously submitted and reviewed and no further action is warranted.

X_____ This document contains substantive information that is summarized below; however, no further regulatory action is warranted.

_____ This document contains substantive information that is summarized below and is essential to the review and maintenance of this license. Further regulatory review or consideration is necessary.

SUMMARY:

The DSG has accepted the groundwater
restoration of Reno Creek Pattern II and
requests DSG administration for release of the
Bond

DATE DUE TO DOCKET FILE:

June 15, 1983