


VERMONT YANKEE NUCLEAR POWER CORPORATION



Ferry Road, Brattleboro, VT 05301-7002

REPLY TO:
ENGINEERING OFFICE
580 MAIN STREET
BOLTON, MA 01740
(508) 779-6711

October 17, 1996
BVY 96-126

United States Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

References: (a) License No. DPR-28 (Docket No. 50-271)
(b) Letter, VYNPC to USNRC, " Revised Schedule for Completing Appendix R
Corrective Actions," BVY 96-117, dated October 8, 1996

Subject: Additional Appendix R Corrective Action

In Reference (b) Vermont Yankee provided a revised schedule for completing its Appendix R corrective actions. Subsequent to submitting Reference (b), Vermont Yankee completed its surveillance of fire barriers and fire rated assemblies and identified one fire penetration seal, located in the Cable Vault, that needs to be repaired. Vermont Yankee will complete the repair following startup and will maintain appropriate compensatory measures until the repair has been completed.

We trust that the information provided is acceptable. However, should you have questions or require additional information, please contact this office.

Sincerely,

VERMONT YANKEE NUCLEAR POWER CORPORATION

James J. Duffy
Licensing Engineer

c: USNRC Region I Administrator
USNRC Project Manager - VYNPS
USNRC Resident Inspector - VYNPS

9610220125 961017
PDR ADOCK 05000271
F PDR

1/0
A006