

APPENDIX A  
NOTICE OF VIOLATION

Connecticut Yankee Power Company  
Haddam Neck Station  
Haddam Neck, Connecticut

Docket No. 50-213  
License No. DPR-61

As a result of the inspection conducted on March 25-29, 1985, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violation was identified:

Environmental Technical Specifications, Section 5.3, "Review and Audit," states, in part, that, "The Environmental Review Board shall make or cause to be made at least semiannual reviews or audits of the following ... Surveillance records, written procedures, and reports required for compliance with these Environmental Technical Specifications."

Contrary to the above, the scope of the 1983 Semiannual Environmental Audit #A20021 failed to include a review of the Annual Environmental Operating Report Part B or the Radioactive Effluents Release Report. Additionally, the scope of the 1983 Semiannual Environmental Audit #A20022 failed to include a review of the Radiological Environmental Monitoring Program surveillance records or the Annual Environmental Operating Report and the Radioactive Effluents Release Report.

This is a Severity Level V violation. (Supplement I)

Pursuant to the provisions of 10 CFR 2.201, Connecticut Yankee Atomic Power is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8506040623 850520  
PDR ADOCK 05000213  
Q PDR

OFFICIAL RECORD COPY