



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV
URANIUM RECOVERY FIELD OFFICE
BOX 25325
DENVER, COLORADO 80225

DATE: 5/9/83

NOTE TO
DOCKET FILE: 40-8714

FROM: Frederick Ross

SUBJECT: REVIEW OF MAIL CONTROL NO. 00168

I have reviewed the subject document and have concluded the following:

- ☐ This document contains information that is not essential to the review and maintenance of this license and no further regulatory review or consideration is warranted.
- ☐ This document contains information that was previously submitted and reviewed and no further action is warranted.
- ☒ This document contains substantive information that is summarized below; however, no further regulatory action is warranted.
- ☐ This document contains substantive information that is summarized below and is essential to the review and maintenance of this license. Further regulatory review or consideration is necessary.

SUMMARY: ^{technical staff} WDEQ has found restoration at CCIC's Collins Draw site to be inadequate

DATE DUE TO DOCKET FILE: APR 20 1983