



BON SECOURS HOSPITAL

June 24, 1985

John E. Glenn, Ph.D.
Chief, Nuclear Materials Safety Section B
Division of Radiation Safety and Safeguards
Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Re: Docket Nos. 030-00247 and 030-13728
License Nos. 20-13916-01 and 20-13916-02
Subject: Inspection Report Nos. 030-00247/85-01
and 030-13728/85-01

Dear Dr. Glenn:

With this letter you will find one dated June 20, 1985 from Jacob Spira, Ph.D. of the Radiation Physics Department at University Hospital, Boston. It speaks to the field area measurements performed on radiation therapy equipment at Bon Secours Hospital on June 18, 1985. Accompanying Dr. Spira's letter is a report indicating the results of those measurements.

I believe this information is what is necessary to bring us into compliance under NRC regulations, however, if further information is needed, please let me know. Thank you for your continued support throughout this process.

Sincerely yours,

Edward G. George, FACHA
Associate Director

EGG/emb
Enclosure

cc: William L. Lane, Director
Mary Ellen Davis, Chief Radiologic Technologist
Candace C. Crowell, Radiation Therapy Department
Jacob Spira, Ph.D., Radiation Physicist
Santos K. Shetty, M.D., Director, Radiation Therapy

8507150410 850710
REG1 LIC30
20-13916-01 PDR